11 S-7	MAILING BY "EXPRESS white, et al	99-65-02 MAIL" (37 CFR 1.10)	Docket No. DLY-014
Serial No. Patent No. 6,401,824	Filing Date Issued 11 June 2002	Examiner	Group Art Unit
	e following correspondence: (General - Patent Issued), and al	l documents referenced therein	
	(Identify type	of correspondence)	
	h the United States Postal Serv evelope addressed to: The Assi つむ ねひと	¥	
		Matt Robi	
		(1ypea or Frunca Name of Person.	Manual Correspondence)
	<u></u>	(Signature of Person Mailing	g Correspondence)

(Signature of Person Mailing Correspondence)

EV 152488343 US

("Express Mail" Mailing Label Number)

Note: Each paper must have its own certificate of mailing.

Certificate
SEP 1 3 2002

of Correction

TRANSMITTALLETTEI (General - Patent Issued)	
Ratemer(s): Musselwhite, et al	
U.S. Patent No.	Issue Date
6,401,824	11 June 2002
itle: Well Completion Convertible Float Shoe/Co.	llar
TO THE ASSISTANT CO	OMMISSIONERFOR PATENTS:
Request for Certificate of Correction Under 35 USC 25 Two (2) Certificate of Correction Forms (one for text & □ No additional fee is required. □ A check in the amount of \$100.00 is at □ The Assistant Commissioner is hereby authorize as described below. A duplicate copy of this she □ Charge the amount of □ Credit any overpayment. □ Charge any additional fee required.	tached. ed to charge and credit Deposit Account No. 13-2166
Guy E. Matthews Reg. No. 24,173 The Matthews Firm (Customer No. 021897) 1900 West Loop South, Suite 1800 Houston, Texas 77027 US 1713-355-4200 Telephone 1713-355-9689 Facsimile	Dated: Certify that this document and fee is being deposited with the U.S. Postal Service as class mail under 37 C.F.R. 1.8 and is addressed to Assistant Commissioner for Patents, Washington, E 20231.
c:	Signature of Person Mailing Correspondence Typed or Printed Name of Person Mailing Correspondence



PRACTITIONER'S DOCKET No.: DLY-014

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE UNITED STATES PATENT NO. 6,401,824 B1

PATENTEES: JEFFREY O. MUSSELWHITE, ET. AL.

ISSUE DATE: 11 JUNE 2002

FOR: "WELL COMPLETION CONVERTIBLE FLOAT SHOE/COLLAR"

REQUEST FOR CERTIFICATE OF CORRECTION UNDER 35 USC 255

HONORABLE COMMISSIONER FOR PATENTS and Trademarks
Washington, D.C. 20231

Sir:

Enclosed is a proposed Certificate of Correction which, for the most part, has been necessitated by the applicant's mistakes.

It is respectfully submitted that each of the mistakes in the Specification is the result of a clerical or typographical nature, and that each of them is of a minor character.

For example, the flapper valves 31 in FIG.s 1, 2 and 3 are illustrated as being open, i.e., inactivated. FIG. 4 illustrates the flapper valves 31 as being closed, i.e., activated. This is described further in Col. 3., lines 46 and 47 and in Col. 3, lines 66 and 67, thus leading to the need to correct Col. 3, line 3 and Col. 3, line 5.

The correction to Col. 3, line 12, is merely typographical.

100 0.00

The element 33A of FIG.'s 1, 2, 3 and 4 is clearly not an upwardly facing jet. The element 33 is the one or more upwardly facing jets, illustrated in FIG.s 1, 2, 3 and 4, thus necessitating the need to correct Col. 3, lines 50 and 51, and Col. 4, line 2.

The correction added to Col. 4, line 14, between "valves." and "The" is merely to clarify and summarize the functions of the float shoe tube 27.

The element 23A in FIG. 1 is clearly not a seat, but rather is a collar through which the ball 23 will fall all the way down to the catcher portion 35 of the inner member 27. As set forth in column 3, lines 29-32, at some point in time, as desired, the ball 23 is dropped from the earth's surface and will travel all the way to the catcher portion 35. In FIG. 1, the ball 23 is illustrated in its dropped position on the way to being seated on the catcher portion 35 and hence the need to clarify the fact that the element 23A is not a seat, as now corrected in Col. 3, lines 29 and 30.

Page 3 of the proposed Certificate of Correction relates to Figs. 2, 3 and 4 of the drawing and the only thing to be accomplished by this correction is the rotation of each of the three figures to indicate the true top end 14 of each drawing relating to the tool.

The other errors, those found in the claims, primarily resulted from mistakes covered by 35 USC 254, occurring within the United States Patent and Trademark Office, as evidenced by the copy of the application Claims 1-10 and 15-22, as were allowed.

None of the proposed corrections is believed to constitute new matter, or is of a nature to require re-examination. Moreover, every one of the applicants' mistakes occurred in good faith.

Accordingly, the patentees courteously solicit the issuance of the enclosed Certificate of Correction. The requisite fee of \$100.00 is enclosed. Should such enclosed fee be inadvertently separated from this request, or be less than the required amount, the

Commissioner is authorized to charge any insufficiency to Deposit Account No. 13-2166, for which duplicate copies of this authorization are enclosed.

Respectfully submitted,

Guy E. Matthews

Reg. No. 24,173

THE MATTHEWS FIRM

1900 West Loop South, Suite 1800

Houston, Texas 77027

(713) 355-4200 - Telephone

(713) 355-9689 - Facsimile